


rys.1



rys.2

d (mm)	M6	M6	M8
D (mm)	12	15	17
k (mm)	3,0	3,8	4
s (mm)	4	4 nebo 5	5
L (mm)			
20	.		
25			
30	.		
35			
40	.		
45			
50	.	.	.
55			
60	.	.	.